

**TURBIDITY MEASURED MONTHLY AT SEVEN STATIONS
AND THREE DEPTHS AT THE KONA BLUE OFFSHORE SITE.**
SEE ATTACHED AERIAL PHOTO FOR STATION LOCATIONS

The overall pattern is one of occasional, marginal increases in turbidity at the midwater Effluent station (E), compared with other depths and stations i.e. up-current (C1 and C2), and down-current of the farm site (Z1 - Z4)

